

Oil Field Environmental Incident Summary

Incident: 20160630100139 **Date/Time of Notice:** 06/30/2016 10:01

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 44-1004H CTB

Field Name: PARSHALL

Well File #:

Date Incident: 6/29/2016 **Time Incident:** 10:42 **Facility ID Number:** 227042-01

County: MOUNTRAIL **Twp:** 152 **Rng:** 90 **Sec:** 10 **Qtr:** SE SE

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	10	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/3/2016

Clean Up Concluded: 7/5/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The liquids were removed with vac truck and the tank has been isolated for repairs. The affected area will be washed with fresh water and liquids will be removed and area will continue to be monitored for any further cleanup actions.

Wastes Disposal Location: SWD

Agencies Involved: TAT, MHA

Updates

Date: 6/30/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.